

U 100 □□ □□ □□□□ IR□□□□ □□□□□□□□

□□□□□□:


□□□□□□□□:

□□□□□□
 □□(□)
 □□□□(Ra)
 □□□□□□□□□□□□
 □□
 □□□□(V)
 □□□□□□(lm/w)

5000
80
AC220V(±10%)
80









U shape Heat Lamp

- A, Fast Heating
- B, High Purify Quartz
- C, Tungsten, Carbon fiber, Ruby quartz.....
- D, U Shape



Ruby Infrared Lamp

Carbon fiber Filaments
30% Energy saving
Far Infrared wave



Application field

1. Electric Heater Parts
2. PET Blowing Machine Parts
3. Painting lacquer drying parts.
4. Textile Heating dryer lamps
5. Drying machine ir oven lamps
6. Oven Electric heater replace lamps
7. Electrons parts drying tube parts.
8. PCB, Glasses, Car, Shrink Machine.....



□□□□:

